

# Troubleshoot pH sensor

## Note

1. The meter is a professional instrument, please use it under professional instructions to prevent it to be damaged.
2. Avoid high temperature and sun exposure.
3. The meter is not waterproof, do not throw the instrument into the solution or make the solution over the immersion line.

## Auto Shut-off Function

The meter will automatically shut down to save battery power if you do not press any key within 5 minutes.

## LowBatt

When the screen display value is blurred or invisible, the battery should be replaced a new one.

## Attention

1. When the value of screen is trapped at 0000 or 7.00 or any other fixed value. please take battery out and reset. then re-calibrate the meter.
2. When test the solution, you must turn on the meter in the air first, then put it into the testing solution.

